


# Kleines Desk Tray | mit USB-Adapter

## CAD Folien


.dwg CAD files available to download from pCon  
Catalog/pCon.Box  
OFML data available on all pCon platforms



## Maßzeichnungen



1. Put the drawer under the worksurface and pull out the drawer
2. Screw the box to the worksurface



Every effort has been made to ensure that information provided in this document is up to date and accurate. However, Fellowes cannot guarantee and assumes no legal liability or responsibility for the accuracy or completeness of the information provide. In case of any query please contact us as [www.Fellowes.com/locations](http://www.Fellowes.com/locations).